



Certification Body: SATRA Technology Certire, Kettering, NN16 85D, UK

Notified Body: 0321

These products are classed as Personal Projective Equipment by the European PPE Directive 89/686/EEC

CAREFULLY READ INSTRUCTIONS BEFORE USE

This product is designed to provide protection against: Mechanical Risks, Thermal Risks and Welding. No item of PPE can provide full protection - care must always be taken whilst carrying out the activity.

EN 420:2003+A1:2009 Protective Gloves – General Requirements
Fitting & Sizing: Only wear products of a suitable size. Products which are either too loose or too tight will restrict movement and will not provide the optimum level of protection.

Storage & Transport: Store the product in a well ventilated area away from extremes of temperature & strong odours.

Inspection Before & After Use: Discard and replace damage products before use. If in doubt consult manufacturer.

## Cleaning: It is recommended that this product should not be washed or dry cleaned

## EN 388:2003

Test	Level Achieved	Level Achieved Maximum Level
Abrasion Resistance	1, 1	(4)
Blade Cut Resistance	2	(5)
Tear Resistance	3	(4)
Puncture Resistance		(4)

**Note:** Performance levels apply to the palm area of the hand.

Warning: These gloves will not prevent crushing injuries, or injuries associated with vibration. They are not to be worn when there is a risk of entanglement by moving parts of machinery.

EN 388:2003

EN 407:2004
Protective Gloves Against Thermal Risks (Heat &/or Fire)

Property	Level Achieved	Maximum Level
Burning Behaviour	×	(4)
Contact Heat	2	(4)
Convective Heat	×	(4)
Radiant Heat	×	(4)
Small Splashes of Molten Metal	×	(4)
Large Quantities of Molten Metal	×	(4)

Warning: The glove must not come in contact with a naked flame, if the glove has a performance level 1 or 2 in burning behaviour.

EN 407:2004

X2XXXX

Supertouch®, Unit A1 Hubert Road, Brentwood, Essex, CM14 4JE Northan Body: SATRA Technology Centre, Kettering, Northamptonshire, UK, NN16 BSD